Make	TATA		
Model	SUPER ACE	1.4 TCIC DLS P/U D/S	
Vin	MAT483131	GYR02317	
Engine Specifications	1.4	Diesel	•
Vehicle Type	D/S		
Service Plan	N/A		

Year	2017
Km	85559
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	<b>~</b>	Aircon Controls	Not Applicable	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	<b>-</b>	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	-Select-		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	-Select-		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Not Applicable		Alternator Belt	Not Applicable	•
Spark Plugs	Not Applicable   ▼		Power Steering Belt	-Select-	•
Brake Fluid	Good Condition		Aircon Belt	Not Applicable	•
Antifreeze	Good Condition		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks  ▼		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks   ▼		PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	-Select-	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	<b>~</b>
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	-
Rear Drums	Within Specification	-
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Within Specification	-
Brake Calipers	Good Condition	-
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	<b>~</b>
Thermostat	Within Specification	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	•
Aircon Condensor	Not Applicable	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Renewed	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	<b>~</b>
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>~</b>
Power Steering Pump	-Select-	<b>V</b>
Wheel Alignment	Within Specification	<b>V</b>
CV Joints	-Select-	<b>V</b>
CV Boots	-Select-	<b>V</b>
Shocks Front	Good Condition	<b>V</b>
Shock Mountings Front	Good Condition	lacksquare
Shocks Rear	-Select-	<b>V</b>
Stabilizer Links	Good Condition	lacksquare
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	<b>V</b>
Control Arms	Good Condition	<b>V</b>
Sideshafts/Seal	No Visible Leaks	<b>V</b>
Propshaft	Within Specification	<b>V</b>
Wheel Nuts/Studs	Good Condition	<b>V</b>
Tyres & Spare	Good Condition	<b>V</b>
Mag Wheels/Hub Caps	Good Condition	<b>V</b>

Transmission & Clutch		
Clutch Kit	Renewed	<b>—</b>
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	
Clutch Cable	Within Specification	-
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	lacksquare
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	<b>~</b>
Road Test	Good Condition	-
Handling	Good Condition	<b>V</b>

Concluding Remarks		

Bosch Technician	
-Select-	_

General Comments		

NEW Technician		
RIAAN MEINTJIES		

Date of Inspection

10-Apr-2024



