



Make	SUZUKI		Year	2022
Model	SWIFT 1.2 GL		Km	71914
Vin	MBHCZC63S00971753		Transmission	Manual <input type="checkbox"/>
Engine Specifications	1.2	Petrol <input type="checkbox"/>	Colour	red
Vehicle Type			Branch	Bosch Car Service
Service Plan			Warranty Plan	

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>	Mag Wheels	Acceptable for vehicle <input type="checkbox"/>
Side Mirrors / Electric	Within Specification	Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine			Km
Oil Service			
Oil Filter	Within Specification <input type="checkbox"/>		
Fuel/Diesel Filter	No Fault Codes <input type="checkbox"/>		
Air Filter	Within Specification <input type="checkbox"/>		
Cabin Filter	Very Good <input type="checkbox"/>		
Spark Plugs	Within Specification <input type="checkbox"/>		
Brake Fluid	No Leaks <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Very Good	Level ok with required coolant ratio	
Rear Main Seal	No Leaks		
Sump/Gasket	No Leaks		
Dip Stick	Within Specification		



Oil Filler Cap	No Leaks		Sealed with no leaks
Fan Belt	No Fault Codes	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Within Specification	<input type="checkbox"/>	
Power Steering Belt	Very Good	<input type="checkbox"/>	
Aircon Belt	Within Specification	<input type="checkbox"/>	
Multi V belt	No Fault Codes	<input type="checkbox"/>	
Engine Mountings	Within Specification		
PCV Valve	Within Specification		Working as per manufacturers specification

Braking System		
Front Brake Pads	Very Good	50 %
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	Not Applicable	0 %
Rear Brake Discs	Not Applicable	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Within Specification	<input type="checkbox"/>
Rear Linings	Within Specification	<input type="checkbox"/>
Brake Master	Within Specification	
Hand Brake	Within Specification	<input type="checkbox"/>
Brake Calipers	Within Specification	
Brake Hose	Very Good	

Cooling System		
Radiator	No Leaks	
Radiator Hoses	No Leaks	
Waterpump	No Leaks	
Thermostat	No Leaks	
Aircon Gas	Very Good	
Aircon Pump	No Leaks	
Aircon Condensor	Very Good	
Interior Fan	Very Good	
Interior Radiator	Within Specification	

Fueling System		
Intake Manifold	No Leaks	
Throttle	Within Specification	
Turbo	Not Applicable	<input type="checkbox"/>
Carburetor	Not Applicable	<input type="checkbox"/>
Injectors	Very Good	<input type="checkbox"/>
Fuel Pump	Within Specification	
Fuel Lines	No Leaks	

Ignition System		
Ignition Coils	Within Specification	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>



Steering & Suspension	
Steering Rack	Within Specification
Power Steering Pump	Within Specification <input type="checkbox"/>
Wheel Alignment	Within Specification
CV Joints	Very Good
CV Boots	Very Good
Shocks Front	No Leaks
Shock Mountings Front	Very Good
Shocks Rear	No Leaks
Stabilizer Links	Very Good
Wheel Bearings	Within Specification
Bearing Hubs	Within Specification
Control Arms	Within Specification
Sideshafts/Seal	No Fault Codes <input type="checkbox"/>
Propshaft	Not Applicable <input type="checkbox"/>
Wheel Nuts/Studs	Very Good
Tyres & Spare	Within Specification
Mag Wheels/Hub Caps	Very Good

Transmission & Clutch	
Clutch Kit	Within Specification <input type="checkbox"/>
Clutch Master	Very Good <input type="checkbox"/>
Clutch Slave	No Fault Codes <input type="checkbox"/>
Clutch Cable	Not Applicable
Gearbox	Within Specification <input type="checkbox"/>
Gear & Diff oil	No Fault Codes <input type="checkbox"/>
Auto Transmission	Not Applicable <input type="checkbox"/>
Gear Selector	Very Good <input type="checkbox"/>
Gear Linkages	Within Specification <input type="checkbox"/>

Ignition System	
Diagnostics	Within Specification <input type="checkbox"/>
Cyl Leakage Test	Within Specification <input type="checkbox"/>
Test Drive	Very Good
Handling	Very Good

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Basal Johnson	<input type="checkbox"/>

Date of Inspection
2023-12-16



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060