



Make	VOLVO	
Model	XC60 D5 INSCRIPTION GEARTRONIC AWD	
Vin	YV1DZ97A6H2049826	
Engine Specifications	2.5	Diesel <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	Not Applicable	

Year	2016	
Km	98731	
Transmission	Automatic	<input type="checkbox"/>
Colour	SILVER	
Branch	Bosch Car Service	
Warranty Plan	Not Applicable	

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	No visible damages <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>	Mag Wheels	No visible damages <input type="checkbox"/>
Side Mirrors / Electric	No Fault Codes <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

## BOSCH VEHICLE INSPECTION

### Engine

Oil Service			DUE FOR SERVICE	Km
Oil Filter	No Leaks <input type="checkbox"/>			
Fuel/Diesel Filter	No Leaks <input type="checkbox"/>			
Air Filter	Within Specification <input type="checkbox"/>			
Cabin Filter	Within Specification <input type="checkbox"/>			
Spark Plugs	Not Applicable <input type="checkbox"/>			
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants		
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio		
Rear Main Seal	No Leaks <input type="checkbox"/>			
Sump/Gasket	No Leaks <input type="checkbox"/>			
Dip Stick	Within Specification <input type="checkbox"/>			



Oil Filler Cap	No Leaks	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Within Specification	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Within Specification	<input type="checkbox"/>	
Power Steering Belt	Within Specification	<input type="checkbox"/>	
Aircon Belt	Within Specification	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Very Good	<input type="checkbox"/>	Working as per manufacturers specification

Braking System		
Front Brake Pads	Within Specification <input type="checkbox"/>	77 %
Front Brake Discs	Within Specification <input type="checkbox"/>	
Front Brake Sensor	Not Applicable <input type="checkbox"/>	
Rear Brake Pads	Renewed <input type="checkbox"/>	100 %
Rear Brake Discs	Within Specification <input type="checkbox"/>	
Rear Brake Sensor	Not Applicable <input type="checkbox"/>	
Rear Drums	Not Applicable <input type="checkbox"/>	
Rear Linings	Not Applicable <input type="checkbox"/>	
Brake Master	No Leaks <input type="checkbox"/>	
Hand Brake	No Fault Codes <input type="checkbox"/>	
Brake Calipers	No Leaks <input type="checkbox"/>	
Brake Hose	No Leaks <input type="checkbox"/>	

Cooling System		
Radiator	No Leaks <input type="checkbox"/>	
Radiator Hoses	No Leaks <input type="checkbox"/>	
Waterpump	No Leaks <input type="checkbox"/>	
Thermostat	Within Specification <input type="checkbox"/>	
Aircon Gas	No Leaks <input type="checkbox"/>	
Aircon Pump	Within Specification <input type="checkbox"/>	
Aircon Condensor	No Fault Codes <input type="checkbox"/>	
Interior Fan	Within Specification <input type="checkbox"/>	
Interior Radiator	Within Specification <input type="checkbox"/>	

Fueling System		
Intake Manifold	No Leaks <input type="checkbox"/>	
Throttle	No Fault Codes <input type="checkbox"/>	
Turbo	No Fault Codes <input type="checkbox"/>	
Carburetor	Not Applicable <input type="checkbox"/>	
Injectors	No Fault Codes <input type="checkbox"/>	
Fuel Pump	No Fault Codes <input type="checkbox"/>	
Fuel Lines	No Leaks <input type="checkbox"/>	

Ignition System		
Ignition Coils	Not Applicable <input type="checkbox"/>	
Glow Plugs	No Fault Codes <input type="checkbox"/>	
Distributor	Not Applicable <input type="checkbox"/>	
HT Leads	Not Applicable <input type="checkbox"/>	



Steering & Suspension		
Steering Rack	No Leaks	<input type="checkbox"/>
Power Steering Pump	No Fault Codes	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	No Leaks	<input type="checkbox"/>
Shocks Front	No Leaks	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	No Fault Codes	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Leaks	<input type="checkbox"/>
Propshaft	Within Specification	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Renewed	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	No Fault Codes	<input type="checkbox"/>
Gear & Diff oil	No Leaks	<input type="checkbox"/>
Auto Transmission	No Fault Codes	<input type="checkbox"/>
Gear Selector	Within Specification	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Codes	<input type="checkbox"/>
Cyl Leakage Test	No Leaks	<input type="checkbox"/>
Test Drive	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Dries Olwagan	<input type="checkbox"/>



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060