

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:johan@boschgezina.co.za
Sn:988579800333
Time:2023-12-29 07:43:03
Technician Name:Dries
Customer Name:cittoncars

Vehicle Information

Year:2017
Make:VOLVO
Model:XC60
VIN:YV1DZ97A6H2049826
Displacement:D 1.5 VGT U2
Odometer:98735 km
Vehicle Software Version:V10.18

Inspection Result

The following systems are OK:

- 1.AUD (Audio Module)
- 2.CCM (Climate Control Module)
- 3.DDM (Driver Door Module)
- 4.KVM (Keyless Vehicle Module)
- 5.PAC (Parking Assistance Camera)
- 6.PDM (Passenger Door Module)
- 7.POT (Power Operated Tailgate Module)
- 8.PSM (Power Seat Module)
- 9.TRM (Trailer Module)
- 10.ICM (Infotainment Control Module)
- 11.ABS (Anti-Lock Braking System)
- 12.CEM (Central Electrical Module)
- 13.CVM (Closing Velocity Module)
- 14.DEM (Differential Electronic Module)
- 15.DIM (Driver Information Module)
- 16.PAM (Park Assist Module)
- 17.PBM (Park Brake Module)
- 18.SAS (Steering Wheel Angle Sensor Module)
- 19.SRS (Supplemental Inflatable Restraint System)
- 20.TCM (Transmission Control Module)
- 21.DIESEL ENG (Fuel System/Combined System)
- 22.PSCM (Power Steering Control Module)