



Make	TOYOTA		Year	2019
Model	COROLLA QUEST 1.6		Km	83499
Vin	AHTLB52E203140128		Transmission	Manual <input type="checkbox"/>
Engine Specifications	1.6	Petrol <input type="checkbox"/>	Colour	SILVER
Vehicle Type	S/D		Branch	Bosch Car Service
Service Plan	Not Applicable		Warranty Plan	Not Applicable

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	No visible damages <input type="checkbox"/>	Mag Wheels	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine			
Oil Service		2022-09-21	61141 Km
Oil Filter	-Select- <input type="checkbox"/>		SERVICE DUE
Fuel/Diesel Filter	-Select- <input type="checkbox"/>		
Air Filter	-Select- <input type="checkbox"/>		
Cabin Filter	-Select- <input type="checkbox"/>		
Spark Plugs	-Select- <input type="checkbox"/>		
Brake Fluid	No Leaks <input type="checkbox"/>		Clean & free of contaminants
Antifreeze	No Leaks <input type="checkbox"/>		Level ok with required coolant ratio
Rear Main Seal	No Leaks <input type="checkbox"/>		
Sump/Gasket	No Leaks <input type="checkbox"/>		
Dip Stick	No Leaks <input type="checkbox"/>		



Oil Filler Cap	No Leaks	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Within Specification	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Not Applicable	<input type="checkbox"/>	
Power Steering Belt	Not Applicable	<input type="checkbox"/>	
Aircon Belt	Not Applicable	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System		
Front Brake Pads	Within Specification <input type="checkbox"/>	70 %
Front Brake Discs	Within Specification <input type="checkbox"/>	
Front Brake Sensor	Not Applicable <input type="checkbox"/>	
Rear Brake Pads	Within Specification <input type="checkbox"/>	80 %
Rear Brake Discs	Within Specification <input type="checkbox"/>	
Rear Brake Sensor	Not Applicable <input type="checkbox"/>	
Rear Drums	Not Applicable <input type="checkbox"/>	
Rear Linings	Not Applicable <input type="checkbox"/>	
Brake Master	Within Specification <input type="checkbox"/>	
Hand Brake	Within Specification <input type="checkbox"/>	
Brake Calipers	No Leaks <input type="checkbox"/>	
Brake Hose	No Leaks <input type="checkbox"/>	

Cooling System		
Radiator	No Leaks <input type="checkbox"/>	
Radiator Hoses	-Select- <input type="checkbox"/>	
Waterpump	-Select- <input type="checkbox"/>	
Thermostat	-Select- <input type="checkbox"/>	
Aircon Gas	-Select- <input type="checkbox"/>	
Aircon Pump	-Select- <input type="checkbox"/>	
Aircon Condensor	No Leaks <input type="checkbox"/>	
Interior Fan	Within Specification <input type="checkbox"/>	
Interior Radiator	No Leaks <input type="checkbox"/>	

Fueling System		
Intake Manifold	No Leaks <input type="checkbox"/>	
Throttle	No Leaks <input type="checkbox"/>	
Turbo	Not Applicable <input type="checkbox"/>	
Carburetor	Not Applicable <input type="checkbox"/>	
Injectors	No Leaks <input type="checkbox"/>	
Fuel Pump	Within Specification <input type="checkbox"/>	
Fuel Lines	No Leaks <input type="checkbox"/>	

Ignition System		
Ignition Coils	Within Specification <input type="checkbox"/>	
Glow Plugs	Not Applicable <input type="checkbox"/>	
Distributor	Not Applicable <input type="checkbox"/>	
HT Leads	Not Applicable <input type="checkbox"/>	



Steering & Suspension		
Steering Rack	No Leaks	<input type="checkbox"/>
Power Steering Pump	No Leaks	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	No Leaks	<input type="checkbox"/>
CV Boots	No Leaks	<input type="checkbox"/>
Shocks Front	Within Specification	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	Within Specification	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Within Specification	<input type="checkbox"/>
Clutch Master	Within Specification	<input type="checkbox"/>
Clutch Slave	Within Specification	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	Within Specification	<input type="checkbox"/>
Gear & Diff oil	No Leaks	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Not Applicable	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Codes	<input type="checkbox"/>
Cyl Leakage Test	No Leaks	<input type="checkbox"/>
Test Drive	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Luandre Swanepoel	<input type="checkbox"/>

Date of Inspection
2023-12-22



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060