



Make	HYUNDAI		Year	2021
Model	VENUE 1.0 TGDI FLUID DCT		Km	34036
Vin	MALFC81AVLM111797		Transmission	Automatic <input type="checkbox"/>
Engine Specifications	1.0	Petrol <input type="checkbox"/>	Colour	GREY
Vehicle Type	SUV		Branch	Bosch Car Service
Service Plan	30/04/2024		Warranty Plan	06/04/2028

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>	Mag Wheels	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		26472 Km
Oil Filter	Within Specification <input type="checkbox"/>	
Fuel/Diesel Filter	Within Specification <input type="checkbox"/>	
Air Filter	Within Specification <input type="checkbox"/>	
Cabin Filter	Within Specification <input type="checkbox"/>	
Spark Plugs	Within Specification <input type="checkbox"/>	
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio
Rear Main Seal	Within Specification <input type="checkbox"/>	
Sump/Gasket	Within Specification <input type="checkbox"/>	
Dip Stick	Within Specification <input type="checkbox"/>	



Oil Filler Cap	Within Specification	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Within Specification	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Within Specification	<input type="checkbox"/>	
Power Steering Belt	Within Specification	<input type="checkbox"/>	
Aircon Belt	Within Specification	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	Within Specification	<input type="checkbox"/>	%
Front Brake Discs	Within Specification	<input type="checkbox"/>	
Front Brake Sensor	Within Specification	<input type="checkbox"/>	
Rear Brake Pads	Within Specification	<input type="checkbox"/>	%
Rear Brake Discs	Within Specification	<input type="checkbox"/>	
Rear Brake Sensor	Within Specification	<input type="checkbox"/>	
Rear Drums	-Select-	<input type="checkbox"/>	
Rear Linings	-Select-	<input type="checkbox"/>	
Brake Master	Within Specification	<input type="checkbox"/>	
Hand Brake	Within Specification	<input type="checkbox"/>	
Brake Calipers	Within Specification	<input type="checkbox"/>	
Brake Hose	Within Specification	<input type="checkbox"/>	

Cooling System			
Radiator	Within Specification	<input type="checkbox"/>	
Radiator Hoses	Within Specification	<input type="checkbox"/>	
Waterpump	Within Specification	<input type="checkbox"/>	
Thermostat	Within Specification	<input type="checkbox"/>	
Aircon Gas	Within Specification	<input type="checkbox"/>	
Aircon Pump	Within Specification	<input type="checkbox"/>	
Aircon Condensor	Within Specification	<input type="checkbox"/>	
Interior Fan	Within Specification	<input type="checkbox"/>	
Interior Radiator	Within Specification	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Within Specification	<input type="checkbox"/>	
Throttle	Within Specification	<input type="checkbox"/>	
Turbo	Within Specification	<input type="checkbox"/>	
Carburetor	-Select-	<input type="checkbox"/>	
Injectors	Within Specification	<input type="checkbox"/>	
Fuel Pump	Within Specification	<input type="checkbox"/>	
Fuel Lines	Within Specification	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Within Specification	<input type="checkbox"/>	
Glow Plugs	-Select-	<input type="checkbox"/>	
Distributor	-Select-	<input type="checkbox"/>	
HT Leads	-Select-	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Within Specification	▼
CV Joints	Within Specification	▼
CV Boots	Within Specification	▼
Shocks Front	Within Specification	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	Within Specification	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	Within Specification	▼
Propshaft	-Select-	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Within Specification	▼
Clutch Master	Within Specification	▼
Clutch Slave	-Select-	▼
Clutch Cable	-Select-	▼
Gearbox	Within Specification	▼
Gear & Diff oil	Within Specification	▼
Auto Transmission	Within Specification	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	Within Specification	▼
Cyl Leakage Test	Within Specification	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Ricardo Myburgh	▼

Date of Inspection
2024-01-18



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060