

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton Cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:juan-dre@boschgezina.co.za  
Sn:988579800333  
Time:2024-02-22 11:19:43  
Technician Name:Raymond  
Customer Name:refilwe

## Vehicle Information

Make:NISSAN  
Displacement:G 1.6 DOHC  
Odometer:111878 miles  
Vehicle Software Version:V10.32

## Inspection Result

The following systems are OK:

- 1.ENGINE
- 2.ABS
- 3.BCM
- 4.AIR BAG
- 5.EPS/DAST 3