



Make	HAVAL		Year	2019
Model	H2 1.5T LUXURY		Km	62733
Vin	LGWEE4A48KH909101		Transmission	Manual <input type="checkbox"/>
Engine Specifications	1.5	Petrol <input type="checkbox"/>	Colour	WHITE
Vehicle Type	SUV		Branch	Bosch Car Service
Service Plan	N/A		Warranty Plan	15/07/2024

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	No visible damages <input type="checkbox"/>	Mag Wheels	No visible damages <input type="checkbox"/>
Side Mirrors / Electric	Very Good <input type="checkbox"/>	Wiper Blades	No visible damages <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service			Km
Oil Filter	Very Good <input type="checkbox"/>		
Fuel/Diesel Filter	-Select- <input type="checkbox"/>		
Air Filter	Very Good <input type="checkbox"/>		
Cabin Filter	Very Good <input type="checkbox"/>		
Spark Plugs	Very Good <input type="checkbox"/>		
Brake Fluid	No Leaks <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	No Leaks <input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	No Leaks <input type="checkbox"/>		
Sump/Gasket	No Leaks <input type="checkbox"/>		
Dip Stick	Very Good <input type="checkbox"/>		



Oil Filler Cap	Very Good	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Very Good	<input type="checkbox"/>	
Fan belt Tensioner	Very Good	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Very Good	<input type="checkbox"/>	
Power Steering Belt	Very Good	<input type="checkbox"/>	
Aircon Belt	Very Good	<input type="checkbox"/>	
Multi V belt	Very Good	<input type="checkbox"/>	
Engine Mountings	Very Good	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	-Select-	<input type="checkbox"/>	50 %
Front Brake Discs	Within Specification	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	-Select-	<input type="checkbox"/>	50 %
Rear Brake Discs	Very Good	<input type="checkbox"/>	
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Drums	Not Applicable	<input type="checkbox"/>	
Rear Linings	Not Applicable	<input type="checkbox"/>	
Brake Master	Very Good	<input type="checkbox"/>	
Hand Brake	Very Good	<input type="checkbox"/>	
Brake Calipers	Very Good	<input type="checkbox"/>	
Brake Hose	Very Good	<input type="checkbox"/>	

Cooling System			
Radiator	No Leaks	<input type="checkbox"/>	
Radiator Hoses	No Leaks	<input type="checkbox"/>	
Waterpump	No Leaks	<input type="checkbox"/>	
Thermostat	No Leaks	<input type="checkbox"/>	
Aircon Gas	No Leaks	<input type="checkbox"/>	
Aircon Pump	No Leaks	<input type="checkbox"/>	
Aircon Condensor	No Leaks	<input type="checkbox"/>	
Interior Fan	No Fault Codes	<input type="checkbox"/>	
Interior Radiator	No Leaks	<input type="checkbox"/>	

Fueling System			
Intake Manifold	No Leaks	<input type="checkbox"/>	
Throttle	No Leaks	<input type="checkbox"/>	
Turbo	Within Specification	<input type="checkbox"/>	
Carburetor	Not Applicable	<input type="checkbox"/>	
Injectors	No Leaks	<input type="checkbox"/>	
Fuel Pump	Not Applicable	<input type="checkbox"/>	
Fuel Lines	No Leaks	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Within Specification	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	Not Applicable	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	No Leaks	<input type="checkbox"/>
Wheel Alignment	No Fault Codes	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	No Leaks	<input type="checkbox"/>
Shocks Front	No Leaks	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Very Good	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Within Specification	<input type="checkbox"/>
Clutch Master	No Leaks	<input type="checkbox"/>
Clutch Slave	No Leaks	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	Very Good	<input type="checkbox"/>
Gear & Diff oil	Very Good	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Very Good	<input type="checkbox"/>
Gear Linkages	Very Good	<input type="checkbox"/>

Ignition System		
Diagnostics	Within Specification	<input type="checkbox"/>
Cyl Leakage Test	-Select-	<input type="checkbox"/>
Test Drive	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Basal Johnson	<input type="checkbox"/>

Date of Inspection
2024-01-08



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060