

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: jaco@boschgezina.co.za
Sn: 988579800333
Time: 2024-01-23 15:27:12
Technician Name: Lu-André
Customer Name: Citton cars

Vehicle Information

Make: MITSUBISHI
VIN: MK2LNNC1WLN009590
Displacement: G 1.4 DOHC
Odometer: 16015 km
Vehicle Software Version: V10.28

Inspection Result

The following systems are OK:

1. MPI/GDI/DIESEL
2. 4WS/Electric Power Steering
3. ABS/ASC/ASTC/WSS
4. SRS-Air Bag
5. ETACS
6. KOS/Immo/Keyless
7. Meter