

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:2024-01-16 10:53:04  
Technician Name:Dries  
Customer Name:citton cars

## Vehicle Information

Year:2019.09-  
Make:TOYOTA  
Model:Corolla  
VIN:JTNGY3BE303001892  
Displacement:G 1.6 MPI  
Odometer:56997.00 km  
Vehicle Software Version:V10.40

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECM (Engine Control Module)
- 3.CCS (Cruise Control)
- 4.TCM (Transmission Control Module)
- 5.ABS (Brake Control)/EPB (Electrical Parking Brake)
- 6.EMPS (Electronic Motor Power Steering)
- 7.SAS (Steering Angle Sensor)
- 8.SRS (Supplemental Inflatable Restraint System)
- 9.AC (Air Conditioning)
- 10.CM (Combination Meter)
- 11.SC (Starting Control)
- 12.NS (Navigation System)
- 13.BCM (Body Control Module)
- 14.ES (Entry&Start)
- 15.CGW (Central Gateway)
- 16.DDM (Driver Door Motor)
- 17.PDM (Passenger Door Motor)
- 18.RLDM (Rear Left Door Motor)
- 19.RRDM (Rear Right Door Motor)
- 20.MSW (Master Switch)
- 21.PSC (Power Source Control)