

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: lukas@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-01-29 15:40:15  
Technician Name: Lardus  
Customer Name: cittoncars

## Vehicle Information

Year: 2018  
Make: NISSAN  
Model: nivara  
VIN: MNTCB2D23Z0000379  
Displacement: G 1.2 MPI  
Odometer: 44993 km  
Vehicle Software Version: V10.32

## Inspection Result

HVAC 1 problems exist

1. B2631-00 Sunload Sensor

CRNT

The following systems are OK:

1. ENGINE
2. ABS
3. METER/M&A
4. BCM
5. AIR BAG
6. TRANSMISSION
7. MULTI AV
8. IPDM E/R
9. DIFF LOCK
10. SONAR
11. LANE CAMERA