



BOSCH INSPECTION REPORT

BOSCH JC#: 11471

Make	FORD		Year	2013	
Model	ECOSPORT 1.0 ECOBOOST TITANIUM		Km	106901	
Vin	MAJAXXMRKADG44525		Transmission	Automatic	
Engine Specifications	1.0	Petrol	Colour	SILVER	
Vehicle Type	SUV		Branch	Bosch Car Service	
Service Plan	N/A		Warranty Plan	N/A	

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order	Aircon Controls	In good working order
Cluster	In good working order	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order	Mag Wheels	Acceptable for vehicle
Side Mirrors / Electric	Within Specification	Wiper Blades	In good working order

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km
Oil Filter	No Leaks	
Fuel/Diesel Filter	No Leaks	
Air Filter	Within Specification	
Cabin Filter	Within Specification	
Spark Plugs	Within Specification	
Brake Fluid	No Leaks	Clean & free of contaminants
Antifreeze	No Leaks	Level ok with required coolant ratio
Rear Main Seal	No Leaks	
Sump/Gasket	No Leaks	
Dip Stick	No Leaks	



BOSCH INSPECTION REPORT

BOSCH JC#: 11471

Oil Filler Cap	No Leaks	Sealed with no leaks
Fan Belt	No Fault Codes	
Fan belt Tensioner	Within Specification	No noise from tensioner
Alternator Belt	No Fault Codes	
Power Steering Belt	No Fault Codes	
Aircon Belt	No Fault Codes	
Multi V belt	No Fault Codes	
Engine Mountings	Within Specification	
PCV Valve	Within Specification	Working as per manufacturers specification

Braking System		
Front Brake Pads	-Select-	60 %
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	%
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	
Rear Drums	Within Specification	
Rear Linings	-Select-	80%
Brake Master	Within Specification	
Hand Brake	Within Specification	
Brake Calipers	Within Specification	
Brake Hose	Within Specification	

Cooling System		
Radiator	No Leaks	
Radiator Hoses	No Leaks	
Waterpump	No Leaks	
Thermostat	No Leaks	
Aircon Gas	No Leaks	
Aircon Pump	No Leaks	
Aircon Condensor	No Leaks	
Interior Fan	Within Specification	
Interior Radiator	No Leaks	

Fueling System		
Intake Manifold	Within Specification	
Throttle	Within Specification	
Turbo	Within Specification	
Carburetor	Not Applicable	
Injectors	Within Specification	
Fuel Pump	Within Specification	
Fuel Lines	Within Specification	

Ignition System		
Ignition Coils	Within Specification	
Glow Plugs	Not Applicable	
Distributor	Not Applicable	
HT Leads	Within Specification	



BOSCH INSPECTION REPORT

BOSCH JC#: 11471

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	No Leaks	▼
Wheel Alignment	Within Specification	
CV Joints	Within Specification	▼
CV Boots	No Leaks	▼
Shocks Front	No Leaks	
Shock Mountings Front	Within Specification	▼
Shocks Rear	No Leaks	
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	
Control Arms	Within Specification	
Sideshafts/Seal	No Leaks	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Within Specification	▼
Clutch Master	Within Specification	▼
Clutch Slave	Within Specification	▼
Clutch Cable	Within Specification	▼
Gearbox	Within Specification	▼
Gear & Diff oil	Within Specification	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	Within Specification	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

Final Notes & Comments
<p>This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions</p>

Bosch Technician	
Lardus Erasmus	▼

Date of Inspection
2024-02-01



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
t: 012 335 5737
e: reception@boschgezina.co.za

