



Make	HYUNDAI	
Model	CRETA 1.4 TGDI EXECUTIVE DCT	
Vin	MALPB811VMM106894	
Engine Specifications	1.4	Diesel <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	01/06/2025	

Year	2021	
Km	52341	
Transmission	Automatic <input type="checkbox"/>	
Colour	GREY	
Branch	Bosch Car Service	
Warranty Plan	24/06/2028	

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order
Cluster	In good working order

Aircon Controls	In good working order
Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Very Good <input type="checkbox"/>

Mag Wheels	Acceptable for vehicle <input type="checkbox"/>
Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service			Km
Oil Filter	Very Good <input type="checkbox"/>		
Fuel/Diesel Filter	Very Good <input type="checkbox"/>		
Air Filter	Very Good <input type="checkbox"/>		
Cabin Filter	Very Good <input type="checkbox"/>		
Spark Plugs	Very Good <input type="checkbox"/>		
Brake Fluid	Very Good <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Very Good <input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	Very Good <input type="checkbox"/>		
Sump/Gasket	Very Good <input type="checkbox"/>		
Dip Stick	Very Good <input type="checkbox"/>		



Oil Filler Cap	Very Good	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Very Good	<input type="checkbox"/>	
Fan belt Tensioner	Very Good	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Very Good	<input type="checkbox"/>	
Power Steering Belt	Very Good	<input type="checkbox"/>	
Aircon Belt	Very Good	<input type="checkbox"/>	
Multi V belt	Very Good	<input type="checkbox"/>	
Engine Mountings	Very Good	<input type="checkbox"/>	
PCV Valve	Very Good	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	-Select-	<input type="checkbox"/>	60 %
Front Brake Discs	Very Good	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	-Select-	<input type="checkbox"/>	60 %
Rear Brake Discs	Very Good	<input type="checkbox"/>	
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Drums	Not Applicable	<input type="checkbox"/>	
Rear Linings	-Select-	<input type="checkbox"/>	
Brake Master	Very Good	<input type="checkbox"/>	
Hand Brake	Very Good	<input type="checkbox"/>	
Brake Calipers	Very Good	<input type="checkbox"/>	
Brake Hose	Very Good	<input type="checkbox"/>	

Cooling System			
Radiator	Very Good	<input type="checkbox"/>	
Radiator Hoses	Very Good	<input type="checkbox"/>	
Waterpump	Very Good	<input type="checkbox"/>	
Thermostat	Very Good	<input type="checkbox"/>	
Aircon Gas	Very Good	<input type="checkbox"/>	
Aircon Pump	Very Good	<input type="checkbox"/>	
Aircon Condensor	Very Good	<input type="checkbox"/>	
Interior Fan	Very Good	<input type="checkbox"/>	
Interior Radiator	Very Good	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Very Good	<input type="checkbox"/>	
Throttle	Very Good	<input type="checkbox"/>	
Turbo	Very Good	<input type="checkbox"/>	
Carburetor	Very Good	<input type="checkbox"/>	
Injectors	Very Good	<input type="checkbox"/>	
Fuel Pump	Very Good	<input type="checkbox"/>	
Fuel Lines	Very Good	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Very Good	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	Very Good	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	Very Good	▼
Power Steering Pump	Very Good	▼
Wheel Alignment	Very Good	▼
CV Joints	Very Good	▼
CV Boots	Very Good	▼
Shocks Front	Very Good	▼
Shock Mountings Front	Very Good	▼
Shocks Rear	Very Good	▼
Stabilizer Links	Very Good	▼
Wheel Bearings	Very Good	▼
Bearing Hubs	Very Good	▼
Control Arms	Very Good	▼
Sideshafts/Seal	Very Good	▼
Propshaft	Not Applicable	▼
Wheel Nuts/Studs	Very Good	▼
Tyres & Spare	Very Good	▼
Mag Wheels/Hub Caps	Very Good	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Very Good	▼
Gear & Diff oil	Very Good	▼
Auto Transmission	Very Good	▼
Gear Selector	Not Applicable	▼
Gear Linkages	Not Applicable	▼

Ignition System		
Diagnostics	Very Good	▼
Cyl Leakage Test	Very Good	▼
Test Drive	Very Good	▼
Handling	Very Good	▼

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Basal Johnson	▼

Date of Inspection
2024-01-29



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060