

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-02-15 14:58:18
Technician Name:Raymond
Customer Name:fedi paulos

Vehicle Information

Year:2018
Make:CHANGCHENG
Model:HAVAL H2 2019(CN6)
VIN:LGWEE4A49JH903922
Displacement:G 1.4 T-GDI
Odometer:109516 miles
Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Liandian GDI VI)(4G15F)
- 2.ESP (Electrical Stable Program)(Brake)
- 3.SRS (Supplemental Inflatable Restraint System)
- 4.IP (Instrument Panel)
- 5.AC (Air Conditioning)
- 6.BCM (Body Control Module)
- 7.PEPS (Passive Entry Passive Start System)
- 8.GW (Independent Gateway)
- 9.ESCL (Electronic Steering Control Lock)
- 10.EPS (Electric Power Steering System)
- 11.SAS (Steering Angle Sensor)
- 12.CMS (CAN Message Switchover System)(Abroad)