

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: johan@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-01-24 13:07:54  
Technician Name: Adriaan  
Customer Name: Citton cars

## Vehicle Information

Year: 2019  
Make: VOLVO  
Model: XC60 (18-)  
VIN: LYVUZA8ACKB205902  
Displacement: G 1.8 MPI  
Odometer: 63177 km  
Vehicle Software Version: V10.18

## Inspection Result

The following systems are OK:

1. CEM (Central Electrical Module)
2. DIESEL ENG (Fuel System/Combined System)
3. TCM (Transmission Control Module)
4. ABS (Anti-Lock Braking System)
5. SRS (Supplemental Inflatable Restraint System)
6. DIM (Driver Information Module)
7. CCM (Climate Control Module)
8. BBS (Battery Backed-Up Sounder)
9. IMS (Interior Motion Sensor)
10. SWM (Steering Wheel Module)
11. DEM (Differential Electronic Module)
12. SCL (Steering Column Lock)
13. PSMD (Power Seat Module-Driver)
14. PSMP (Power Seat Module-Passenger)
15. SUM (Suspension Module)
16. AUD (Audio Module)
17. SAS (Steering Wheel Angle Sensor Module)
18. SODL (Side Obstacle Detection Control Module Left)
19. SODR (Side Obstacle Detection Control Module Right)
20. BMS (Battery Monitoring System)
21. CCD (Center Console Display)
22. PSCM (Power Steering Control Module)
23. OHC (Over Head Console)

- 24.POT (Power Operated Tailgate Module)
- 25.VDDM (Vehicle Dynamic Domain Master)
- 26.WAM (Wide Angle Vision Module)
- 27.RML (Restraint Module-Left)
- 28.RMR (Restraint Module-Right)
- 29.DDM (Driver Door Module)
- 30.PDM (Passenger Door Module)
- 31.IHU (Infotainment Head Unit)
- 32.ASDM (Active Safety Domain Master)
- 33.VCM (Vehicle Communication Module)
- 34.GSM (Gearshift Module)
- 35.HCML (Headlight Control Module Left)
- 36.HCMR (Headlight Control Module Right)