



Make	VOLVO	
Model	XC60 D4 INSCRIPTION GEARTRONIC AWD	
Vin	LYVUZA8ACKB205902	
Engine Specifications		Diesel <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2019	
Km	63152	
Transmission	Automatic	<input type="checkbox"/>
Colour	GREY	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order	<input type="checkbox"/>	Aircon Controls	In good working order	
Cluster	In good working order	<input type="checkbox"/>	Electric Windows	In good working order	

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order	<input type="checkbox"/>	Mag Wheels	In good working order	<input type="checkbox"/>
Side Mirrors / Electric	Within Specification	<input type="checkbox"/>	Wiper Blades	In good working order	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service			59612	Km
Oil Filter	Within Specification	<input type="checkbox"/>		
Fuel/Diesel Filter	Within Specification	<input type="checkbox"/>		
Air Filter	Within Specification	<input type="checkbox"/>		
Cabin Filter	Within Specification	<input type="checkbox"/>		
Spark Plugs	Not Applicable	<input type="checkbox"/>		
Brake Fluid	Within Specification	<input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Within Specification	<input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	No Leaks	<input type="checkbox"/>		
Sump/Gasket	No Leaks	<input type="checkbox"/>		
Dip Stick	Within Specification	<input type="checkbox"/>		



Oil Filler Cap	Within Specification	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Not Applicable	<input type="checkbox"/>	
Fan belt Tensioner	Not Applicable	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Not Applicable	<input type="checkbox"/>	
Power Steering Belt	Not Applicable	<input type="checkbox"/>	
Aircon Belt	Not Applicable	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System		
Front Brake Pads	Within Specification	<input type="checkbox"/> %
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Within Specification	<input type="checkbox"/>
Rear Brake Pads	Within Specification	<input type="checkbox"/> %
Rear Brake Discs	Within Specification	<input type="checkbox"/>
Rear Brake Sensor	Within Specification	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	Not Applicable	<input type="checkbox"/>
Brake Master	Within Specification	<input type="checkbox"/>
Hand Brake	Within Specification	<input type="checkbox"/>
Brake Calipers	No Leaks	<input type="checkbox"/>
Brake Hose	No Leaks	<input type="checkbox"/>

Cooling System		
Radiator	No Leaks	<input type="checkbox"/>
Radiator Hoses	No Leaks	<input type="checkbox"/>
Waterpump	Within Specification	<input type="checkbox"/>
Thermostat	Within Specification	<input type="checkbox"/>
Aircon Gas	Within Specification	<input type="checkbox"/>
Aircon Pump	Within Specification	<input type="checkbox"/>
Aircon Condensor	Within Specification	<input type="checkbox"/>
Interior Fan	Within Specification	<input type="checkbox"/>
Interior Radiator	No Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	Within Specification	<input type="checkbox"/>
Throttle	Within Specification	<input type="checkbox"/>
Turbo	Within Specification	<input type="checkbox"/>
Carburetor	Not Applicable	<input type="checkbox"/>
Injectors	Within Specification	<input type="checkbox"/>
Fuel Pump	Within Specification	<input type="checkbox"/>
Fuel Lines	No Leaks	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	Within Specification	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>



Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Renewed	▼
CV Joints	Within Specification	▼
CV Boots	Within Specification	▼
Shocks Front	Within Specification	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	Within Specification	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	Within Specification	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Within Specification	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Not Applicable	▼
Gear & Diff oil	Within Specification	▼
Auto Transmission	Within Specification	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	Not Applicable	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Adriaan Rademeyer	▼

Date of Inspection
2024-01-24



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060