Make	VOLKSWAGE	N	
Model	POLO 1.0 TSI COMFORTLINE		
Vin	AAVZZZAWZJ	IU064626	
Engine Specifications	1.0	Petrol	•
Vehicle Type	H/B		
Service Plan	N/A		

Year	2018
Km	129308
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	-
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	_	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SE	RVICE DUE Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	V
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	~
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	~
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	~	Aircon Belt	Good Condition	~
Antifreeze	Good Condition	~	Multi V belt	Good Condition	~
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	~
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Good Condition	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	~
Throttle	Good Condition	V
Turbo	Good Condition	—
Injectors	Good Condition	•
Fuel Pump	Good Condition	▼
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Good Condition	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	—
Wheel Alignment	Good Condition	—
CV Joints	Good Condition	—
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	—
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	—
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	—
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	
Road Test	Good Condition	-
Handling	Good Condition	-

Concluding Remarks	

Bosch Technician	
Luandre Swanepoel	¥

General Comments			

NEW Technician		

Date of Inspection

08-Feb-2024



