

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-02-09 13:48:39
Technician Name:Raymond
Customer Name:Citton Cars

Vehicle Information

Make:RENAULT
Model:KWID
VIN:MEEBBA003K8689173
Displacement:G 2.0 MPI-NU
Odometer:54677 km
Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.IC (Instrument Cluster)
- 4.UCH
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.Variable P.A.S
- 7.Radio