



Make	NISSAN		Year	2022
Model	NP200 1.6 P/U S/C		Km	51908
Vin	ADNUSN1D5U0206013		Transmission	Manual <input type="checkbox"/>
Engine Specifications	1.6	Petrol <input type="checkbox"/>	Colour	WHITE
Vehicle Type	C/PS/C		Branch	Bosch Car Service
Service Plan	N/A		Warranty Plan	13/05/2028

Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order	Aircon Controls	In good working order
Cluster	In good working order	Electric Windows	In good working order

Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>	Mag Wheels	Acceptable for vehicle <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		44822 Km
Oil Filter	No Leaks <input type="checkbox"/>	
Fuel/Diesel Filter	-Select- <input type="checkbox"/>	
Air Filter	Within Specification <input type="checkbox"/>	
Cabin Filter	Not Applicable <input type="checkbox"/>	
Spark Plugs	Within Specification <input type="checkbox"/>	
Brake Fluid	No Leaks <input type="checkbox"/>	Clean & free of contaminants
Antifreeze	No Leaks <input type="checkbox"/>	Level ok with required coolant ratio
Rear Main Seal	No Leaks <input type="checkbox"/>	
Sump/Gasket	No Leaks <input type="checkbox"/>	
Dip Stick	Very Good <input type="checkbox"/>	



Oil Filler Cap	No Leaks	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Renewed	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Renewed	<input type="checkbox"/>	
Power Steering Belt	Renewed	<input type="checkbox"/>	
Aircon Belt	Not Applicable	<input type="checkbox"/>	
Multi V belt	Renewed	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	-Select-	<input type="checkbox"/>	60 %
Front Brake Discs	Within Specification	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	-Select-	<input type="checkbox"/>	%
Rear Brake Discs	Not Applicable	<input type="checkbox"/>	
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Drums	Within Specification	<input type="checkbox"/>	
Rear Linings	-Select-	<input type="checkbox"/>	80%
Brake Master	No Leaks	<input type="checkbox"/>	
Hand Brake	Within Specification	<input type="checkbox"/>	
Brake Calipers	No Leaks	<input type="checkbox"/>	
Brake Hose	No Leaks	<input type="checkbox"/>	

Cooling System			
Radiator	No Leaks	<input type="checkbox"/>	
Radiator Hoses	No Leaks	<input type="checkbox"/>	
Waterpump	Within Specification	<input type="checkbox"/>	
Thermostat	Within Specification	<input type="checkbox"/>	
Aircon Gas	Not Applicable	<input type="checkbox"/>	
Aircon Pump	Not Applicable	<input type="checkbox"/>	
Aircon Condensor	Not Applicable	<input type="checkbox"/>	
Interior Fan	Within Specification	<input type="checkbox"/>	
Interior Radiator	No Leaks	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Within Specification	<input type="checkbox"/>	
Throttle	Within Specification	<input type="checkbox"/>	
Turbo	Not Applicable	<input type="checkbox"/>	
Carburetor	Within Specification	<input type="checkbox"/>	
Injectors	Within Specification	<input type="checkbox"/>	
Fuel Pump	Within Specification	<input type="checkbox"/>	
Fuel Lines	No Leaks	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Within Specification	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	No Fault Codes	<input type="checkbox"/>	



BOSCH INSPECTION REPORT

BOSCH JC#: 11456

Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Within Specification	▼
CV Joints	Within Specification	▼
CV Boots	No Leaks	▼
Shocks Front	No Leaks	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	No Leaks	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Renewed	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	No Leaks	▼
Propshaft	Not Applicable	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Within Specification	▼
Clutch Master	No Leaks	▼
Clutch Slave	No Leaks	▼
Clutch Cable	Not Applicable	▼
Gearbox	Within Specification	▼
Gear & Diff oil	No Leaks	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Very Good	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	No Leaks	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

Final Notes & Comments

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Raymond Mncube	▼

Date of Inspection
2024-01-25



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084
 t: 012 335 5737
 e: reception@boschgezina.co.za



AC-MI4006060