



Make	FORD	
Model	ECOSPORT 1.5TIVCT AMBIENTE AT	
Vin	MAJAXXMRKAMD72127	
Engine Specifications	1.5	Diesel <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	23/03/2026	

Year	2022	
Km	55885	
Transmission	Automatic	<input type="checkbox"/>
Colour	WHITE	
Branch	Bosch Car Service	
Warranty Plan	28/03/2026	

Interior

Radio / Entertainment	Good Condition	<input type="checkbox"/>	Aircon Controls	Good Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Good Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Good Condition	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	SERVICE DUE Km		Dip Stick	Good Condition	<input type="checkbox"/>
Oil Filter	Good Condition	<input type="checkbox"/>	Oil Filler Cap	Good Condition	<input type="checkbox"/>
Fuel/Diesel Filter	Good Condition	<input type="checkbox"/>	Fan Belt	Good Condition	<input type="checkbox"/>
Air Filter	Good Condition	<input type="checkbox"/>	Fan belt Tensioner	Good Condition	<input type="checkbox"/>
Cabin Filter	Good Condition	<input type="checkbox"/>	Alternator Belt	Good Condition	<input type="checkbox"/>
Spark Plugs	Good Condition	<input type="checkbox"/>	Power Steering Belt	Good Condition	<input type="checkbox"/>
Brake Fluid	Good Condition	<input type="checkbox"/>	Aircon Belt	Good Condition	<input type="checkbox"/>
Antifreeze	No Visible Leaks	<input type="checkbox"/>	Multi V belt	Good Condition	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	-Select-	<input type="button" value="v"/>
Front Brake Discs	Good Condition	<input type="button" value="v"/>
Front Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Brake Pads	-Select-	<input type="button" value="v"/>
Rear Brake Discs	Not Applicable	<input type="button" value="v"/>
Rear Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Drums	Good Condition	<input type="button" value="v"/>
Rear Linings	-Select-	<input type="button" value="v"/>
Brake Master	Good Condition	<input type="button" value="v"/>
Hand Brake	Good Condition	<input type="button" value="v"/>
Brake Calipers	Good Condition	<input type="button" value="v"/>
Brake Hose	Good Condition	<input type="button" value="v"/>

Cooling System		
Radiator	Good Condition	<input type="button" value="v"/>
Radiator Hoses	Good Condition	<input type="button" value="v"/>
Waterpump	Good Condition	<input type="button" value="v"/>
Thermostat	Good Condition	<input type="button" value="v"/>
Aircon Gas	Good Condition	<input type="button" value="v"/>
Aircon Pump	Good Condition	<input type="button" value="v"/>
Aircon Condensor	Good Condition	<input type="button" value="v"/>
Interior Fan	Good Condition	<input type="button" value="v"/>
Interior Radiator	Good Condition	<input type="button" value="v"/>

Fueling System		
Intake Manifold	Good Condition	<input type="button" value="v"/>
Throttle	Good Condition	<input type="button" value="v"/>
Turbo	-Select-	<input type="button" value="v"/>
Injectors	Good Condition	<input type="button" value="v"/>
Fuel Pump	Good Condition	<input type="button" value="v"/>
Fuel Lines	Good Condition	<input type="button" value="v"/>

Ignition System		
Ignition Coils	Good Condition	<input type="button" value="v"/>
Glow Plugs	Not Applicable	<input type="button" value="v"/>
Distrubutor	Not Applicable	<input type="button" value="v"/>
HT Leads	Not Applicable	<input type="button" value="v"/>

Steering & Suspension		
Steering Rack	Good Condition	▼
Power Steering Pump	Good Condition	▼
Wheel Alignment	Good Condition	▼
CV Joints	Good Condition	▼
CV Boots	Good Condition	▼
Shocks Front	Good Condition	▼
Shock Mountings Front	Good Condition	▼
Shocks Rear	Good Condition	▼
Stabilizer Links	Good Condition	▼
Wheel Bearings	Good Condition	▼
Bearing Hubs	Good Condition	▼
Control Arms	Good Condition	▼
Sideshafts/Seal	No Visible Leaks	▼
Propshaft	Not Applicable	▼
Wheel Nuts/Studs	Good Condition	▼
Tyres & Spare	Good Condition	▼
Mag Wheels/Hub Caps	Good Condition	▼

Transmission & Clutch		
Clutch Kit	Good Condition	▼
Clutch Master	Good Condition	▼
Clutch Slave	Good Condition	▼
Clutch Cable	Not Applicable	▼
Gearbox	Good Condition	▼
Gear & Diff oil	-Select-	▼
Auto Transmission	-Select-	▼
Gear Selector	Good Condition	▼
Gear Linkages	Good Condition	▼

Ignition System		
Diagnostics	-Select-	▼
Cyl Leakage Test	-Select-	▼
Road Test	-Select-	▼
Handling	-Select-	▼

Concluding Remarks	

Bosch Technician
-Select-

General Comments

NEW Technician

Date of Inspection