

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton Cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:2024-02-10 11:56:31  
Technician Name:Lardus  
Customer Name:bosch

## Vehicle Information

Year:2022  
Make:VW\_CV  
VIN:WV1ZZZ7JZNX020251  
Displacement:G 1.1 SOHC  
Odometer:83453 km  
Vehicle Software Version:V10.23

## Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.22 All-Wheel Drive Electronics
- 10.44 Power Steering
- 11.5F Information Electronics 1
- 12.69 Trailer Function