

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:jaco@boschgezina.co.za
Sn:988579800333
Time:2024-01-31 15:22:23
Technician Name:zandre
Customer Name:cittoncars

Vehicle Information

Make:CITROEN
Model:C3 (B618)
VIN:VF7SXHNVTLT525762
Displacement:G 2.0 MPI
Odometer:57595 km
Vehicle Software Version:V10.18

Inspection Result

The following systems are OK:

- 1.Built-in System Interface (BSI)
- 2.Engine System
- 3.Gearbox
- 4.Anti-lock Brake System
- 5.Air Bag
- 6.Parking Assistance
- 7.Battery Charge Status Unit
- 8.Air Conditioning
- 9.Control Panel
- 10.Voltage Retaining Device
- 11.Multiplexed Control Panel
- 12.Switch Module Under The Steering Wheel(Top Of Column)
- 13.Siren
- 14.Multifunction Video Camera(CMF)
- 15.Audio-navigation Or Telematic Unit Or Connected Audio System
- 16.Electric Power Steering