

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-01-29 16:41:19
Technician Name:Lardus
Customer Name:cittoncars

Vehicle Information

Year:2018
Make:NISSAN
Model:NAVARA
VIN:ADNCCAD23ZOO12456
Displacement:G 1.2 MPI
Odometer:44993 miles
Vehicle Software Version:V10.32

Inspection Result

HVAC 1 problems exist

1.B2631-00 Sunload Sensor

CRNT

The following systems are OK:

- 1.ENGINE
- 2.ABS
- 3.METER/M&A
- 4.BCM
- 5.AIR BAG
- 6.TRANSMISSION
- 7.MULTI AV
- 8.IPDM E/R
- 9.DIFF LOCK
- 10.SONAR
- 11.LANE CAMERA