Make	LEXUS		
Model	IS 200T EX/300 EX		
Vin	JTHBA1D2205022672	2	
Engine Specifications	2.0	Petrol	\blacksquare
Vehicle Type	2.0 S/D	Petrol	_

Year	2013
Km	128543
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	—	Aircon Controls	Within Specification	•
Cluster	Within Specification	lacksquare	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Within Specification	-

	BOSCH VEHIC	:LI	E INSPECTION	
Engine				
Oil Service	SERVICE DUE Km		Dip Stick	No Visible Leaks ▼
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks ▼
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks ▼
Air Filter	Within Specification		Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification		Alternator Belt	No Cracks ▼
Spark Plugs	Within Specification		Power Steering Belt	No Cracks
Brake Fluid	Within Specification		Aircon Belt	No Cracks
Antifreeze	Within Specification		Multi V belt	No Cracks
Rear Main Seal	Within Specification		Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification

Braking System		
Front Brake Pads	40%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	40%	•
Rear Brake Discs	Within Specification	~
Rear Brake Sensor	Within Specification	•
Rear Drums	Not Applicable	lacksquare
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	V
Brake Calipers	Within Specification	v
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	No Visible Leaks	—
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Visible Leaks	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	lacksquare
Turbo	Within Specification	lacksquare
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	No Visible Leaks	lacksquare
Wheel Alignment	Within Specification	
CV Joints	Within Specification	
CV Boots	Within Specification	
Shocks Front	No Visible Leaks	
Shock Mountings Front	Within Specification	
Shocks Rear	No Visible Leaks	
Stabilizer Links	Within Specification	
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	
Control Arms	Within Specification	
Sideshafts/Seal	No Visible Leaks	
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	V

Concluding Remarks		

Bosch Technician	
Lardus Erasmus	•

General Comments		

NEW Technician		

Date of Inspection
28-Feb-2024



