

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-02-27 13:12:37
Technician Name:Lardus
Customer Name:bosch

Vehicle Information

Year:-2016.10
Make:LEXUS
Model:IS200t
VIN:JTHBA1D2205022672
Displacement:G 1.4 DOHC
Odometer:128543.00 km
Vehicle Software Version:V10.44

Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECM (Engine Control Module)
- 3.CCS (Cruise Control)
- 4.TCM (Transmission Control Module)
- 5.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 6.EMPS (Electronic Motor Power Steering)
- 7.SRS (Supplemental Inflatable Restraint System)
- 8.AC (Air Conditioning)
- 9.CM (Combination Meter)
- 10.SC (Starting Control)
- 11.NS (Navigation System)
- 12.TT (Tilt&Telescopic)
- 13.TPMS (Tire Pressure Monitoring System)
- 14.BCM (Body Control Module)
- 15.HAL (HL AutoLeveling)
- 16.ES (Entry&Start)
- 17.GWS (Gateway System)
- 18.DDM (Driver Door Motor)
- 19.PDM (Passenger Door Motor)
- 20.RLDM (Rear Left Door Motor)
- 21.RRDM (Rear Right Door Motor)
- 22.MSW (Master Switch)
- 23.PSC (Power Source Control)

24.CS (Clearance Sonar)