

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-02-13 11:35:20
Technician Name:zandre
Customer Name:cittoncars

Vehicle Information

Make:VW
VIN:WVGZZZ5NZJW854203
Displacement:G 1.4 DOHC
Odometer:118441 km
Vehicle Software Version:V10.22

Inspection Result

The following systems are OK:

1.01 Engine Electronics
2.02 Transmission Electronics
3.03 Brake Electronics
4.08 Climate Control Module
5.09 Electronic Central Electric
6.15 Airbag
7.16 Steering Column Electronics Systems
8.17 Instrument Cluster
9.19 Data Bus OBD Interface
10.20 High Beam Assistant
11.22 All-Wheel Drive Electronics
12.42 Driver's Door Electronics
13.44 Power Steering
14.52 Passenger's Door Electronics
15.55 Headlamp Range Control
16.5F Information Electronics 1
17.65 Tire Pressure Monitoring System (TPMS)
18.69 Trailer Function
19.6D Rear Lid Electronics
20.76 Parking Aid
21.CA Sunroof Control Module