Make	GWM		
Model	STEED 5 2.0 WGT WORKHORSE P/U S/C		
Vin	LGWCBD378MB6557	09	
Engine Specifications	2.0	Diesel	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2021
Km	116112
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	—	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	V	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable		Power Steering Belt	No Cracks	•
Brake Fluid	Good Condition		Aircon Belt	No Cracks	•
Antifreeze	Good Condition		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	lacksquare
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	lacksquare
Rear Linings	100%	lacksquare
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	—
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	$ \mathbf{v} $
Interior Fan	Within Specification	lacksquare
Interior Radiator	No Visible Leaks	V

Fueling System		
Intake Manifold	Within Specification	•
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	V

Ignition System		
Ignition Coils	Not Applicable	—
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	—
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	No Visible Leaks	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	No Visible Leaks	
Clutch Slave	No Visible Leaks	
Clutch Cable	Not Applicable	
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



