



Make	TOYOTA	
Model	RAV4 2.0 GX A/T	
Vin	JTMZD3EV10J163042	
Engine Specifications	2.0	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2018
Km	92770
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order
Cluster	In good working order

Aircon Controls	In good working order
Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>

Mag Wheels	Acceptable for vehicle <input type="checkbox"/>
Wiper Blades	In good working order <input type="checkbox"/>

# BOSCH VEHICLE INSPECTION

## Engine

Oil Service		28/08/2024 72452 Km
Oil Filter	Within Specification <input type="checkbox"/>	
Fuel/Diesel Filter	Within Specification <input type="checkbox"/>	
Air Filter	Within Specification <input type="checkbox"/>	
Cabin Filter	Within Specification <input type="checkbox"/>	
Spark Plugs	Within Specification <input type="checkbox"/>	
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio
Rear Main Seal	No Leaks <input type="checkbox"/>	
Sump/Gasket	No Leaks <input type="checkbox"/>	
Dip Stick	Within Specification <input type="checkbox"/>	



Oil Filler Cap	Within Specification	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	No Fault Codes	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	No Fault Codes	<input type="checkbox"/>	
Power Steering Belt	No Fault Codes	<input type="checkbox"/>	
Aircon Belt	No Fault Codes	<input type="checkbox"/>	
Multi V belt	No Fault Codes	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System			
Front Brake Pads	-Select-	<input type="checkbox"/>	100 %
Front Brake Discs	Renewed	<input type="checkbox"/>	
Front Brake Sensor	Not Applicable	<input type="checkbox"/>	
Rear Brake Pads	-Select-	<input type="checkbox"/>	60 %
Rear Brake Discs	Within Specification	<input type="checkbox"/>	
Rear Brake Sensor	Within Specification	<input type="checkbox"/>	
Rear Drums	Within Specification	<input type="checkbox"/>	
Rear Linings	-Select-	<input type="checkbox"/>	80%
Brake Master	No Leaks	<input type="checkbox"/>	
Hand Brake	Within Specification	<input type="checkbox"/>	
Brake Calipers	No Leaks	<input type="checkbox"/>	
Brake Hose	No Leaks	<input type="checkbox"/>	

Cooling System			
Radiator	No Leaks	<input type="checkbox"/>	
Radiator Hoses	No Leaks	<input type="checkbox"/>	
Waterpump	No Leaks	<input type="checkbox"/>	
Thermostat	Within Specification	<input type="checkbox"/>	
Aircon Gas	Within Specification	<input type="checkbox"/>	
Aircon Pump	Within Specification	<input type="checkbox"/>	
Aircon Condensor	Within Specification	<input type="checkbox"/>	
Interior Fan	Within Specification	<input type="checkbox"/>	
Interior Radiator	Within Specification	<input type="checkbox"/>	

Fueling System			
Intake Manifold	Within Specification	<input type="checkbox"/>	
Throttle	Within Specification	<input type="checkbox"/>	
Turbo	Not Applicable	<input type="checkbox"/>	
Carburetor	Within Specification	<input type="checkbox"/>	
Injectors	Within Specification	<input type="checkbox"/>	
Fuel Pump	Within Specification	<input type="checkbox"/>	
Fuel Lines	No Fault Codes	<input type="checkbox"/>	

Ignition System			
Ignition Coils	Within Specification	<input type="checkbox"/>	
Glow Plugs	Not Applicable	<input type="checkbox"/>	
Distributor	Not Applicable	<input type="checkbox"/>	
HT Leads	Not Applicable	<input type="checkbox"/>	



Steering & Suspension		
Steering Rack	Within Specification	▼
Power Steering Pump	Within Specification	▼
Wheel Alignment	Within Specification	▼
CV Joints	Within Specification	▼
CV Boots	No Leaks	▼
Shocks Front	No Leaks	▼
Shock Mountings Front	Within Specification	▼
Shocks Rear	No Leaks	▼
Stabilizer Links	Within Specification	▼
Wheel Bearings	Within Specification	▼
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	▼
Sideshafts/Seal	Within Specification	▼
Propshaft	Within Specification	▼
Wheel Nuts/Studs	Within Specification	▼
Tyres & Spare	Within Specification	▼
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	▼
Clutch Master	Not Applicable	▼
Clutch Slave	Not Applicable	▼
Clutch Cable	Not Applicable	▼
Gearbox	Not Applicable	▼
Gear & Diff oil	Within Specification	▼
Auto Transmission	Within Specification	▼
Gear Selector	Within Specification	▼
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Codes	▼
Cyl Leakage Test	Within Specification	▼
Test Drive	Within Specification	▼
Handling	Within Specification	▼

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
-Select-	▼

Date of Inspection
2024-01-30



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060