Make	ISUZU		
Model	D-MAX 1.9 Ddi HR LS A/T D/C P/U		
Vin	ACVTFR87JMD1038	391	
Engine Specifications	1.9	Diesel	\
Vehicle Type	D/C		

Year	2022
Km	42803
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	28/09/2027

Interior					
Radio / Entertainment	Within Specification	~	Aircon Controls	Within Specification	-
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Renewed	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION			
Engine			
Oil Service	SERVICE DUE Km	Dip Stick	Within Specification
Oil Filter	Within Specification	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	Fan Belt	No Cracks ▼
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	Not Applicable ▼
Spark Plugs	Within Specification	Power Steering Belt	Not Applicable
Brake Fluid	Within Specification	Aircon Belt	Not Applicable
Antifreeze	Within Specification	Multi V belt	No Visible Leaks
Rear Main Seal	Within Specification	Engine Mountings	Within Specification
Sump/Gasket	Within Specification	PCV Valve	Within Specification

Braking System		
Front Brake Pads	40%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	Within Specification	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	V
Brake Calipers	Within Specification	~
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	T
Thermostat	Within Specification	-
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	—
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	—
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	V
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	Within Specification	lacksquare
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	—

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	
Clutch Cable	Not Applicable	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Within Specification	
Gear Selector	Within Specification	•
Gear Linkages	Not Applicable	

Ignition System		
Diagnostics	Within Specification	•
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks		

Bosch Technician	
-Select-	¥

General Comments		

NEW Technician	
MCHAEL JONES	

Date of Inspection

06-Feb-2024



