

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: johan@boschgezina.co.za
Sn: 988579800333
Time: 2024-02-02 15:31:34
Technician Name: Dries
Customer Name: cittoncars

Vehicle Information

Make: AUDI
VIN: WAUZZZ8U7HR093452
Odometer: 107433 km
Vehicle Software Version: V10.22

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.10 Parallel Parking 2
- 7.15 Airbag
- 8.16 Steering Column Electronics Systems
- 9.17 Instrument Cluster
- 10.19 Data Bus OBD Interface
- 11.25 Anti-Theft Immobilizer
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.52 Passenger's Door Electronics
- 15.55 Headlamp Range Control
- 16.5F Information Electronics 1
- 17.62 Left Rear Door Electronics
- 18.6D Rear Lid Electronics
- 19.72 Right Rear Door Electronics