



Make	FORD	
Model	EVEREST 2.0D XLT A/T	
Vin	AFAJXXMJWJLS52266	
Engine Specifications	2.0	Diesel <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2021
Km	91678
Transmission	Automatic <input type="checkbox"/>
Colour	CHAMPAGNE
Branch	Bosch Car Service
Warranty Plan	29/12/2025

## Interior

The interior is in good condition , no visible damages

Radio / Entertainment	In good working order <input type="checkbox"/>	Aircon Controls	In good working order
Cluster	In good working order <input type="checkbox"/>	Electric Windows	In good working order

## Exterior

No visible damages, minor imperfections may be present

Windscreen	In good working order <input type="checkbox"/>	Mag Wheels	In good working order <input type="checkbox"/>
Side Mirrors / Electric	Within Specification <input type="checkbox"/>	Wiper Blades	In good working order <input type="checkbox"/>

## BOSCH VEHICLE INSPECTION

### Engine

Oil Service			Km
Oil Filter	Within Specification <input type="checkbox"/>		
Fuel/Diesel Filter	Within Specification <input type="checkbox"/>		
Air Filter	Within Specification <input type="checkbox"/>		
Cabin Filter	Within Specification <input type="checkbox"/>		
Spark Plugs	Not Applicable <input type="checkbox"/>		
Brake Fluid	Within Specification <input type="checkbox"/>	Clean & free of contaminants	
Antifreeze	Within Specification <input type="checkbox"/>	Level ok with required coolant ratio	
Rear Main Seal	Within Specification <input type="checkbox"/>		
Sump/Gasket	Within Specification <input type="checkbox"/>		
Dip Stick	Within Specification <input type="checkbox"/>		



Oil Filler Cap	Within Specification	<input type="checkbox"/>	Sealed with no leaks
Fan Belt	Not Applicable	<input type="checkbox"/>	
Fan belt Tensioner	Within Specification	<input type="checkbox"/>	No noise from tensioner
Alternator Belt	Not Applicable	<input type="checkbox"/>	
Power Steering Belt	Not Applicable	<input type="checkbox"/>	
Aircon Belt	Not Applicable	<input type="checkbox"/>	
Multi V belt	Within Specification	<input type="checkbox"/>	
Engine Mountings	Within Specification	<input type="checkbox"/>	
PCV Valve	Within Specification	<input type="checkbox"/>	Working as per manufacturers specification

Braking System		
Front Brake Pads	Within Specification	<input type="checkbox"/> %
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	Within Specification	<input type="checkbox"/> %
Rear Brake Discs	Within Specification	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	Not Applicable	<input type="checkbox"/>
Brake Master	Within Specification	<input type="checkbox"/>
Hand Brake	Within Specification	<input type="checkbox"/>
Brake Calipers	Within Specification	<input type="checkbox"/>
Brake Hose	Within Specification	<input type="checkbox"/>

Cooling System		
Radiator	No Leaks	<input type="checkbox"/>
Radiator Hoses	No Leaks	<input type="checkbox"/>
Waterpump	Within Specification	<input type="checkbox"/>
Thermostat	No Leaks	<input type="checkbox"/>
Aircon Gas	Within Specification	<input type="checkbox"/>
Aircon Pump	No Leaks	<input type="checkbox"/>
Aircon Condensor	No Leaks	<input type="checkbox"/>
Interior Fan	Within Specification	<input type="checkbox"/>
Interior Radiator	No Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	Within Specification	<input type="checkbox"/>
Throttle	Within Specification	<input type="checkbox"/>
Turbo	Within Specification	<input type="checkbox"/>
Carburetor	Not Applicable	<input type="checkbox"/>
Injectors	Within Specification	<input type="checkbox"/>
Fuel Pump	Within Specification	<input type="checkbox"/>
Fuel Lines	Within Specification	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	Within Specification	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>



Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	Within Specification	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	Within Specification	<input type="checkbox"/>
Shocks Front	Within Specification	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	Within Specification	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	Within Specification	<input type="checkbox"/>
Propshaft	Within Specification	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	Within Specification	<input type="checkbox"/>
Gear & Diff oil	Within Specification	<input type="checkbox"/>
Auto Transmission	Within Specification	<input type="checkbox"/>
Gear Selector	Within Specification	<input type="checkbox"/>
Gear Linkages	Not Applicable	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Codes	<input type="checkbox"/>
Cyl Leakage Test	No Leaks	<input type="checkbox"/>
Test Drive	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

**Final Notes & Comments**

This vehicle inspection has been done impartially and to the best of our knowledge. This Bosch Inspection Report has been applied to all above items and are based the visual inspection and functionality thereof. Bosch cannot be held responsible for any unforeseen or concealed defects. The road test done within the confines of the inspection location. The vehicle is void of visual leaks or engine sludge build up and the vehicle is performing within acceptable and roadworthy conditions

Bosch Technician	
Luandre Swanepoel	<input type="checkbox"/>

Date of Inspection
2024-01-22



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084  
 t: 012 335 5737  
 e: reception@boschgezina.co.za



AC-MI4006060