

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan_dre@boschgezina.co.za
Sn:988579800333
Time:2024-01-16 09:46:43
Technician Name:Basal
Customer Name:citton cars

Vehicle Information

Make:SUZUKI
Model:Baleno
VIN:MBHEWB52S00396299
Displacement:G 2.0 MPI
Odometer:36925 km
Vehicle Software Version:V10.26

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-Lock Braking System)
- 4.EPS (Electronic Power Steering)
- 5.SRS (Supplemental Inflatable Restraint System/Airbag)
- 6.BCM (Body Control Module)
- 7.IPC (Combination Meter / Meter/ M&A)
- 8.CGW (Central Gateway Control Module)