

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-02-19 13:51:20
Technician Name:Lardus
Customer Name:citton cars

Vehicle Information

Make:NISSAN
VIN:ADNUSN1D5U0196471
Displacement:G 1.6 MPI
Odometer:59030 km
Vehicle Software Version:V10.32

Inspection Result

The following systems are OK:

- 1.ABS
- 2.BCM
- 3.AIR BAG