Make	HYUNDAI		
Model	TUCSON 1.6 TGDI ELITE DCT AWD		
Vin	TMAJ3812W0	GJ273876	
Engine Specifications	1.6	Petrol	T
Vehicle Type	SUV		
Service Plan	N/A		

Year	2016
Km	133433
Transmission	Automatic
Colour	GOLD
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	_
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	lacksquare

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	
Oil Filter	Within Specification		Oil Filler Cap	Within Specification	
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	
Brake Fluid	Within Specification		Aircon Belt	No Cracks	
Antifreeze	Within Specification		Multi V belt	No Cracks	
Rear Main Seal	No Visible Leaks ▼		Engine Mountings	Within Specification	
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	T
Interior Fan	No Visible Leaks	-
Interior Radiator	Within Specification	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Within Specification	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	T
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	lacksquare
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	lacksquare
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	No Visible Leaks	lacksquare
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	—
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	~
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	~
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	V

Concluding Remarks		

Bosch Technician	
-Select-	

NEW Technician	
JARDUS	

Date of Inspection

09-Feb-2024



