

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton Cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:2024-02-09 08:53:00  
Technician Name:Lardus  
Customer Name:Citton Cars

## Vehicle Information

Year:2016  
Make:HYUNDAI  
Model:Tucson(TLe)  
VIN:TMAJ3812WGJ273876  
Displacement:G 1.6 T-GDI  
Odometer:133449 km  
Vehicle Software Version:V10.28

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.AC (Air Conditioning)
- 7.Body Control Module
- 8.Cluster Module
- 9.Smart Junction Block
- 10.Power Tail Gate
- 11.C-MDPS(Eastern Europe/General)
- 12.R-MDPS(RHD-Western Europe)
- 13.Driveshaft
- 14.Smart Key Unit
- 15.Blind Spot Detection-Right
- 16.Blind Spot Detection-Left
- 17.CODE (Transmitter Code Saving)