Make	тоуота		
Model	FORTUNER 2.4GD-6 R/B A/T		
Vin	AHTCB3GS9	902003924	
Engine Specifications	2.4	Diesel	V
Vehicle Type	SUV		

Year	2018
Km	99597
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	29/06/2025

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	_
Cluster	Within Specification	—	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	~
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION				
Engine				
Oil Service	SERVICE DUE Km		Dip Stick	No Visible Leaks
Oil Filter	Renewed		Oil Filler Cap	No Visible Leaks ▼
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks ▼
Air Filter	Within Specification		Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification		Alternator Belt	Not Applicable ▼
Spark Plugs	Not Applicable		Power Steering Belt	Not Applicable
Brake Fluid	Within Specification		Aircon Belt	Not Applicable
Antifreeze	Within Specification		Multi V belt	No Cracks
Rear Main Seal	Within Specification		Engine Mountings	Within Specification
Sump/Gasket	Within Specification		PCV Valve	Within Specification

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	100%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	lacksquare
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	lacksquare
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	V
Waterpump	Within Specification	•
Thermostat	No Visible Leaks	V
Aircon Gas	Within Specification	V
Aircon Pump	Within Specification	V
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	V
Interior Radiator	No Visible Leaks	\

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	V
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	T

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	lacksquare
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	
Auto Transmission	Within Specification	lacksquare
Gear Selector	Within Specification	•
Gear Linkages	Not Applicable	

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	—

Concluding Remarks		

Bosch Technician	
Lardus Erasmus	•

General Comments		

NEW Technician	
WIMPIE	

Date of Inspection

24-Feb-2024



