

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:Citton Cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-02-28 13:04:00
Technician Name:Riaan
Customer Name:cittoncars

Vehicle Information

Year:2019
Make:CHANGCHENG
Model:HAVAL H1
VIN:LGWED2A31KE613045
Odometer:75646 km
Vehicle Software Version:V10.28

Inspection Result

The following systems are OK:
1.SRS (Supplemental Inflatable Restraint System)
2.IMMO (Immobilizer System)