

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-09 15:50:28

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Make:RENAULT

Model:KWID

VIN:MEEBBA00700656365

Displacement:G 1.0 MPI KAPPA

Odometer:46478 km

Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.IC (Instrument Cluster)
- 4.UCH
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.Variable P.A.S