Make	ALFA ROMEO)	
Model	MITO 1.4T MULTIAIR DISTINCTIVE		
Vin	ZAR95500001	211935	
Engine Specifications	1.4	Petrol	V
Vehicle Type	SUV		
Service Plan	N/A		

Year	2014
Km	91183
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	~	Aircon Controls	Within Specification	-
Cluster	Within Specification	~	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		91183 Km	Dip Stick	No Visible Leaks	—
Oil Filter	Renewed	-	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	lacksquare	Fan Belt	Not Applicable	•
Air Filter	Within Specification	—	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	—	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	lacksquare	Power Steering Belt	Not Applicable	-
Brake Fluid	Within Specification	_	Aircon Belt	Not Applicable	-
Antifreeze	Renewed	•	Multi V belt	No Cracks	-
Rear Main Seal	No Visible Leaks	lacksquare	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	—

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	-
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	~
Brake Hose	Within Specification	_

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	—
Thermostat	Within Specification	•
Aircon Gas	Within Specification	lacksquare
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	V
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	~

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	lacksquare
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	~
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	-
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	lacksquare

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	-
Clutch Cable	Within Specification	
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	-
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	

Ignition System		
Diagnostics	No Fault Code	~
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	V

Concluding Remarks		

Bosch Technician	
Eugene J.v. Rensburg	•

General Comments		

NEW Technician		

Date of Inspection

11-Mar-2024



