

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-03-14 14:16:13

Technician Name: Ricardo

Customer Name: citton cars

Vehicle Information

Make: NISSAN

Model: NP200

VIN: ADNUSN365U0168699

Odometer: 148118 km

Vehicle Software Version: V10.32

Inspection Result

The following systems are OK:

1. ENGINE

2. ABS

3. BCM

4. AIR BAG

5. EPS/DAST 3