

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: Bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: karika@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-03-11 16:22:45  
Technician Name: mike  
Customer Name: bosch

## Vehicle Information

Year: 2019  
Make: VW  
VIN: WVGZZZ5NZKW376453  
Odometer: 85509 km  
Vehicle Software Version: V10.23

## Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.20 High Beam Assistant
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.55 Headlamp Range Control
- 14.5F Information Electronics 1
- 15.65 Tire Pressure Monitoring System (TPMS)
- 16.69 Trailer Function