

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-03-12 13:34:28
Technician Name: Wimpie F
Customer Name: citton cars

Vehicle Information

Make: NISSAN
Odometer: 128895 km
Vehicle Software Version: V10.32

Inspection Result

The following systems are OK:

1. ENGINE
2. ABS
3. METER/M&A
4. BCM
5. AIR BAG
6. HVAC
7. TRANSMISSION
8. EHS/PKB
9. EPS/DAST 3
10. IPDM E/R
11. AIR PRESSURE MONITOR
12. ALL MODE AWD/4WD
13. CAN GATEWAY
14. CHASSIS CONTROL