Make	HYUNDAI		
Model	VENUE 1.0 TGDI FLUID DCT		
Vin	MALFC81AV	LM102452	
Engine Specifications	1.0	Petrol	-
Vehicle Type	SUV		
Service Plan	N/A		

Year	2021
Km	51938
Transmission	Manual
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	13/12/2025

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	_
Cluster	Within Specification	—	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		42266 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	~	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	—	Fan Belt	Within Specification	•
Air Filter	Within Specification	—	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	—	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	—	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	~	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	lacksquare	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	—	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	—	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	~
Rear Brake Pads	80%	v
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	-Select-	
Rear Linings	-Select-	
Brake Master	Within Specification	~
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	-
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System	
Ignition Coils	Within Specification
Glow Plugs	-Select-
Distrubutor	-Select-
HT Leads	-Select-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	_
Propshaft	-Select-	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	-Select-	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	T

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks		

Bosch Technician	
Raymond Mncube	Ţ

General Comments		

NEW Technician		

Date of Inspection

14-Mar-2024



