

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: Bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-03-14 14:37:46

Technician Name: Ricardo

Customer Name: citton cars

## Vehicle Information

Year: 2020

Make: HYUNDAI

Model: Venue(QXI)

VIN: MALFC81AVLM102452

Displacement: G 1.0 T-GDI KAPPA

Odometer: 51947 km

Vehicle Software Version: V10.30

## Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. TCM (Transmission Control Module)
3. ABS (Anti-lock Braking System)
4. Airbag (Event #1)
5. Airbag (Event #2)
6. AC (Air Conditioning)
7. Integrated Body Control Unit-BCM
8. Integrated Body Control Unit-SMK
9. Integrated Body Control Unit-IMMO
10. IC (Cluster Module)
11. Integrated Body Control Unit-TPMS
12. MDPS (Motor Driven Power Steering)
13. ICCU (Integrated Central Control Unit)
14. CODE (Transmitter Code Saving)