

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: karika@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-03-18 07:11:23  
Technician Name: Basal  
Customer Name: citton cars

## Vehicle Information

Year: 2016.02  
Make: BMW  
Model: X1 sDrive20d  
VIN: WBAHU120305A39629  
Displacement: G 1.2 MPI  
Odometer: 127175 km  
Vehicle Software Version: V10.30

## Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- 3.ZGM (Central Gateway Module)
- 4.ECM (Engine Control Module - DME/DDE)
- 5.TCM (Transmission Control Module - EGS)
- 6.ABS (Anti-Lock Braking System - DSC)
- 7.PMA (Parking Assistant)
- 8.EPS (Electronic Power Steering)
- 9.CAS (Car Access System - CAS/FEM/BDC)
- 10.FZD (Function Center, Roof)
- 11.IC (Instrument Cluster - INSTR)
- 12.ECALL (Emergency Call)
- 13.CIC (Car Information Computer)
- 14.ZBE/CON (Controller)
- 15.AC (Air Conditioning - IHKA)