

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-07-04 07:35:36

Technician Name: Mike Jones

Order no:

Service fee:

Notes:

Vehicle Information

Year: 2020

Make: KIA

Model: Picanto/Morning(JA)

VIN: KNAB3511LLT566578

Displacement: G 1.0 MPI KAPPA

Odometer: 60812 km

Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS/ESC
3. Airbag(Event #1)
4. Airbag(Event #2)
5. AC (Air Conditioning)
6. IC (Instrument Cluster)
7. BCM (Body Control Module)
8. TPMS (Tire Pressure Monitoring System)
9. MDPS (Motor Driven Power Steering)
10. PGS (Parking Guide System)
11. IMMO (Immobilizer)
12. CODE (Transmitter Code Saving)