

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-03-14 13:45:01

Technician Name: Wimpie F

Customer Name: citton cars

Vehicle Information

Make: AUDI

VIN: WAUZZZ8V3H1030792

Odometer: 121755 km

Vehicle Software Version: V10.24

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.16 Steering Column Electronics Systems
- 8.17 Instrument Cluster
- 9.19 Data Bus OBD Interface
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.5F Information Electronics 1
- 14.BB Rear Drivers Side Door Electronics
- 15.BC Rear Passenger Side Door Electronics