Make	MAZDA		
Model	CX-5 2.2DE ACTIVE A/T		
Vin	JM6KF2W2AK030726	5	
Engine Specifications	2.2	-Select-	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2019
Km	84647
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	~	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Working Condition	•

Exterior					
Windscreen	Renewed	—	Mag Wheels	-Select-	
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION				
Engine				
Oil Service	SERVICE DUE Km		Dip Stick	Good Condition
Oil Filter	-Select-		Oil Filler Cap	No Visible Leaks ▼
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	No Cracks ▼
Air Filter	Within Specification		Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification		Alternator Belt	No Cracks ▼
Spark Plugs	Not Applicable		Power Steering Belt	Not Applicable
Brake Fluid	No Visible Leaks ▼		Aircon Belt	No Cracks
Antifreeze	No Visible Leaks		Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification

Braking System		
Front Brake Pads	60%	lacksquare
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	-Select-	
Rear Brake Sensor	Within Specification	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	~
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	T

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	lacksquare
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	~
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	\
Power Steering Pump	Not Applicable	
Wheel Alignment	Within Specification	
CV Joints	Within Specification	
CV Boots	No Visible Leaks	
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	lacksquare
Shocks Rear	No Visible Leaks	
Stabilizer Links	Within Specification	
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	V
Control Arms	Within Specification	
Sideshafts/Seal	No Visible Leaks	~
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	V
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	V

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	-
Clutch Cable	Not Applicable	
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Within Specification	•
Gear Selector	Good Condition	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	—

Concluding Remarks		

Bosch Technician	
Raymond Mncube	•

General Comments		

NEW Technician		

Date of Inspection
17-Mar-2024



