

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:karika@boschgezina.co.za  
Sn:988579800333  
Time:2024-03-22 15:46:58  
Technician Name:shaun  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2017  
Make:TOYOTA  
Model:Corolla  
VIN:AHTBF8JE201007531  
Displacement:G 1.0 MPI KAPPA  
Odometer:65583.00 km  
Vehicle Software Version:V10.44

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 5.EMPS (Electronic Motor Power Steering)
- 6.SRS (Supplemental Inflatable Restraint System)
- 7.AC (Air Conditioning)
- 8.CM (Combination Meter)
- 9.BCM (Body Control Module)
- 10.DDM (Driver Door Motor)
- 11.IMMO (Immobiliser)