

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-03-18 16:33:22
Technician Name:Dries
Customer Name:citton cars

Vehicle Information

Make:VW
VIN:WVGZZZ5NZMM107067
Displacement:G 1.0 MPI KAPPA
Odometer:51988 km
Vehicle Software Version:V10.23

Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.08 Climate Control Module
- 5.09 Electronic Central Electric
- 6.15 Airbag
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.20 High Beam Assistant
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.5F Information Electronics 1
- 14.65 Tire Pressure Monitoring System (TPMS)